Micro Dot Tree Section light checking steps


PLEASE ALWAYS UNPLUG YOUR TREE FIRST BEFORE DO THE FOLLOWING STEPS

1. Find on the unlit section where the connector on the tree pole is. It's on the center of tree pole as shown below


2. hold on the two sides

3. pull out the connector









4. Re-insert the connector back into the tree pole shown below

5. Until you hear a click, meaning that it's connected securely. If you don't hear the click, please push the connector towards the left, to have better connection

