



Micro Dot Tree Branch Lights Checking Steps :

PLEASE ALWAYS UNPLUG YOUR TREE FIRST BEFORE DO THE FOLLOWING STEPS


1. Locate the connector of unlit string on each branch near the pole



2. Pull out the connector by pressing the lock (below arrow)



3. Check the female connector and push the wire back to the female connector if the terminal copper is out of the female connector.



4. Re-insert the connector and push the connector towards the left until hearing a click sound to see if it's a connection issue.

